


## JINAN HONGYANG CNC MACHINERY CO., LTD

### HQD 100W Woodworking Advertising Water-Cooled Spindle Motor

 <p>弘阳数控® HONGYANG CNC</p>	<b>Model:</b>	GDZ-11
	<b>Dimensions:</b>	Φ48*120ΦM/M
	<b>Rotating Speed:</b>	10000-60000RPM
	<b>Power:</b>	0.1KW
	<b>Voltage:</b>	36V
	<b>Frequency:</b>	160-1000HZ
	<b>Bearing:</b>	3 Bearings
	<b>Cooling Method:</b>	Water Cooling
	<b>Chuck Nut:</b>	ER8
	<b>Current:</b>	0.6-1.5A

1. The spindle motor should be used in conjunction with the matched inverter. The specifications and parameters of the inverter should match the related parameters of the spindle motor. If the settings are incorrect, the spindle motor will be burned.
2. Before using, the [water cooled spindle motor](#) must ensure that the cooling circulation system is working normally, and it is strictly prohibited to use the motor without cooling water.
3. During the storage and transportation of the spindle motor, the state of the high-speed grease inside the bearing will change, and the customer should better run the spindle motor at a low speed before its first use.