


JINAN HONGYANG CNC MACHINERY CO., LTD

HQD 300W Woodworking advertising water-cooled spindle

	Model:	GDZ-12
	Dimensions:	Φ48*130ΦM/M
	Rotating Speed:	10000-60000RPM
	Power:	0.3KW
	Voltage:	75V
	Frequency:	160-1000HZ
	Bearing:	3 BEARINGS
	Cooling Method:	WATER COOLING
	Chuck Nut:	ER8
	Current:	2-5A

1. The spindle motor should be used with the inverter. The specifications and parameters of the inverter should match the rated parameters of the spindle motor. If the settings are incorrect, the spindle motor will get burned.
2. Before every use, the water-cooled spindle motor must ensure that the cooling circulation system is still working normally, and it is strictly prohibited to use the [water cooled spindle motor](#) without sufficient cooling water.
3. During the storage and transportation of the spindle motor, the state of the high-speed grease inside the bearing will change; thus, it is better to run the motor in at a low speed before use.

